

Work Status	Completion	Location	Work Completed
	8/1 Completed	Prairie creek 180-170th	Potholes and the approach to the north side of the railway is in rough shape
	8/1 Completed	170th m6	Material added, smoothed out (temporary fix) needs drainage
	8/4 Completed	Shop	Burned brush
	8/4 Completed	Shop	Replaced both front tires on water truck
	8/4 Completed	N meadowlark	Graded/wet down
	8/5 Completed	160th m4/m5	Added material/ Graded
	8/5 Completed	Towakoni	Replaced stop sign
	8/6 Completed	160th m6	Fixed washed out culvert on both sides
	8/6 Completed	M5/M3	Fixed washouts/ holes
	8/6 Completed	Shop	Replaced hydraulic hose on the backhoe
	8/6 Completed	Wells road/166th	Sprayed grass in center of road
	8/6 Completed	120th m6	Scrap wood dumped, removed
	8/7 Completed	Shop	Fixed weed sprayer
	8/7 Completed	160th	Graded/added material
	8/7 Completed	Hillwood addition	Added temporary culvert
	8/8 Completed	160th	Filled, rolled, graded
	8/11 Completed	170th	Washouts filled, rolled and graded
	8/12 Completed	170th	Washouts filled, rolled and graded
	8/13 Completed	County line	Chipseal prep
	8/14 Completed	County line	Rolled, watered and final grade
	8/14 Completed	Meadowlark	Fixed washouts down the middle of the road
	8/14 Completed	Shop	Trash hauled to dump
	8/15 Completed	Queens lace and thistle	Touch ups. Fixed potholes
	8/18 Completed	Wells/166th	Tree trimming
	8/18 Completed	Wells/166th	Resurfaced/prep
	8/18 Completed	County line	Resurfaced/prep
	8/19 Completed	Ruth	Resurfaced/prep
	8/19 Completed	Queens lace/thistle	Resurfaced/prep
	8/19 Completed	Meadowlark (m3)	Resurfaced/prep
	8/19 Completed	11575 SW 170th St	Wash boards and pot holes need to be graded and then a new layer of rock placed.
	8/20 Completed	130th	Graded/material added/wet/packed
	8/20 Completed	170th	Graded/material added/wet/packed
	8/21 Completed	120th and Towakoni	Fixed washouts on
	8/21 Completed	Tawakoni	Fixed bridge/bad washouts just south of bridge
	8/21 Completed	m1 160th	Trash picked up on
	8/22 Completed	Towakoni and 150th	Replaced stop sign
	8/22 Completed	Towakoni	Digging ditches out to fix drainage issue
	8/22 Completed	Shop	Burned brush
	8/25 Completed	Indianola	Cut ditches/fixed drainage issue/smoothed out the road
	8/25 Completed	Indianola	Fixed washouts on edge of road on 170th intersection
	8/26 Completed	Indianola n of 160th	Watered/packed/graded
	8/26 Completed	160th/ponderosa	Fixed drainage issue on culvert and intersection
	8/27 Completed	Indianola	Packed/graded/addedmaterial
	8/27 Completed	160th	Packed/graded
	8/27 Completed	Indianola S of 160th.	road 2 ft low causing drainage and washout issues in driveways.
	8/28 Completed	130th	Packed/graded
	8/28 Completed	160th m6	Packed/graded
	8/28 Completed	Tawakoni m5	Packed/graded
	8/28 Completed	Towakoni m4	Packed/graded
	8/28 Completed	146th	Packed/graded/added material
	8/29 Completed	M5 meadowlark	Asphalt patches on meadowlark
	8/27 Completed	156th/158th	Asphalt patches in potholes, needs more
	8/27 Completed	Meadowlark, 140th, prarie creek, county line	Asphalt patches on Chipseal
	8/27 Completed	Mockingbird	Potholes (15-30 of them)
	Completed	Hillwood, Access road	has been chipsealed, but needs touch up.
	Completed	Thistle/150-sw Queens Lace	chip seal
	Completed	SW Queens Lace/SW 150th	chip seal
	Completed	Ruth Rd 140-143	chip seal
	Completed	143rd Ruth to Butler	chip seal
	Completed	County line 130-140	chip seal
	Completed	Wells Rd / 166th	chip seal
	Completed	Meadowlark North of 150th	chip seal